



546 Bryne Drive, Unit F, Barrie, Ontario, L4N 9P6
Ph. (705) 812-1656 Fx. (705) 812-0947 ~ Email: safety@bellnet.ca

Training, Site Audits, Safety Policy and Programs WSIB Claims Management

PASS THIS ON TO ANY ONE USING ROPE GRABS



September 3, 2008

FP541 Rope Grab Clinch Nut Product Advisory

North Safety Products has received reports that the **clinch nut** on our **FP541 series rope grab** is being dislodged from the body of the rope grab housing in situations where there is repetitive impact to the unit. We have put together a *Product Advisory* document to help ensure that this does not happen in your workplace. Click here to [download the Product Advisory](#).

We are in the process of finalizing our investigation. A second bulletin will be issued in the following weeks which will detail a procedure on how to exchange impacted rope grabs. If you require more information and/or have any further questions or concerns please feel free to contact me.

Yours Truly,

Alex Tsen, P.Eng
Fall Protection Product Manager
North Safety Products
(416) 675-3852 ext 316